

RecyClass

SORTING PROCESS CERTIFICATE

Svensk Plaståtervinning i Motala AB

Registration office address: Vickerkullavagen 2, 591 45 MOTALA

Country: SWEDEN

Plant (-s) Address: see Annex I

The audited Sorting Process and/or Waste Trading Activities and associated management systems have met the requirements of Sorting Process Audit Scheme Version 1.0 and have the required procedures in place to ensure the identification and traceability of the origin of the waste, its suitability for an existing recycling stream and the quality assurance of the Organisation, for the Plastic Waste produced listed in this certificate.

Certification Module:

- ✓ General
- ✓ Alpha: Food Contact
- ☐ Beta: Corporate Social Responsibility

Type of organisation:

- ✓ First Sorting Centre
- ✓ Secondary Sorting Centre
- ☐ Waste Trader

Type of audit: Full-operational (trial audit)

First certificate issue date: 07/10/2025

Country(s) of origin of the Input Waste: EU27+Norway.

Type(s) of collection system of the Input Waste: separate collection, mixed collection, picked from mixed collection.

Type and source of waste: post-consumer, municipal waste, household, industrial, commercial.

Plastic Waste Output: PET, PS, PE, PP, PO, EPS, PVC.

Audit Report and Certificate Code:

SP001-SVE-10-27-ECG-JR

Date of the on-site audit:

25/02/2025

Date of issue of certificate:


07/10/2025

Period of validity*:

07/10/2025 – 06/10/2027

*Validity conditions and terms of use may be found in the Audit Scheme documents.

CERTIFIED BY:



Ms. Zivile Ramoskiene

Legal Representative

ECOGRANT MB

Draugystes st.19,
LT-51230 Kaunas, Lithuania

ECOGRANT

RecyClass

LIST OF CERTIFIED PLASTIC WASTE

Plastic Waste	Pre-consumer or Post-consumer	Type of operation	Collection System	Module
20003 PET bottles	Post-consumer	First Sorting	Separate collection	Alpha
20004 PET trays	Post-consumer	First Sorting	Separate collection	Alpha
20012 PS rigid	Post-consumer	First Sorting	Separate collection	Alpha
20026 PET bottles	Post-consumer	Secondary Sorting	mixed collection	General
20027 PET trays	Post-consumer	Secondary Sorting	mixed collection	General
20028 PS rigid	Post-consumer	Secondary Sorting	mixed collection	General
20002 PE film	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General
20014 PP film	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General
20000 PP rigid	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General
20001 PE rigid	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General

Audit Report and Certificate Code:

SP001-SVE-10-27-ECG-JR

Date of the on-site audit:

25/02/2025

Date of issue of certificate:

07/10/2025

Period of validity*:

07/10/2025 - 06/10/2027

*Validity conditions and terms of use may be found in the Audit Scheme documents.

CERTIFIED BY:



Ms. Zivile Ramoskiene

Legal Representative

ECOGRANT MB

Draugystes st.19,
LT-51230 Kaunas, Lithuania

ECOGRANT

RecyClass

LIST OF CERTIFIED PLASTIC WASTE

Plastic Waste	Pre-consumer or Post-consumer	Type of operation	Collection System	Module
20015 Coloured PET bottles	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General
20009 EPS	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General
20013 PVC	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General
20018 Flexible PO mix	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General
20019 Rigid PO mix	Post-consumer	First and Secondary Sorting	Separate and mixed collection	General

Audit Report and Certificate Code:

SP001-SVE-10-27-ECG-JR

Date of the on-site audit:

25/02/2025

Date of issue of certificate:


07/10/2025

Period of validity*:

07/10/2025 – 06/10/2027

*Validity conditions and terms of use may be found in the Audit Scheme documents.

CERTIFIED BY:



Ms. Zivile Ramoskiene

Legal Representative

ECOGRANT MB

Draugystes st.19,
LT-51230 Kaunas, Lithuania

ECOGRANT

RecyClass

ANNEX I: LIST OF CERTIFIED SITES

Name of the Plant	Address	Country	Date of Audit
Svensk Plaståtervinning i Motala AB	Vickerkullavagen 2, 591 45 MOTALA	SWEDEN	25/02/2025

Audit Report and Certificate Code:

SP001-SVE-10-27-ECG-JR

Date of the on-site audit:

25/02/2025

Date of issue of certificate:


07/10/2025

Period of validity*:

07/10/2025 – 06/10/2027

*Validity conditions and terms of use may be found in the Audit Scheme documents.

CERTIFIED BY:



Ms. Zivile Ramoskiene

Leagal Representantative

ECOGRANT MB

Draugystes st.19,
LT-51230 Kaunas, Lithuania

